

PORT MANSFIELD

CHARLES R JOHNSON (T05) 1 NW UTC-6(-5DT) N26°33.61' W97°26.36' **BROWNSVILLE**
10 B NOTAM FILE SJT L-20H, 21A
RWY 12-30: H3200X50 (ASPH) S-21 MIRL
RWY 12: P-line.
RWY 30: P-line.
SERVICE: LGT SS-SR MIRL Rwy 12-30 preset low intst; to incr intst—CTAF.
AIRPORT REMARKS: Unattended. Harbor superintendent's ofc attended 1400-2250Zt. Deer & birds on & invof arpt. Rwy 12 and Rwy 30 rwy mkg discolored. No public facilities, no restrooms. Fee for ovnght tie down.
AIRPORT MANAGER: 956-944-2325
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Corpus Christi Apch at 361-299-4230.
RADIO AIDS TO NAVIGATION: NOTAM FILE HRL.
HARLINGEN (VL) (DH) VORW/DME 113.65 HRL Chan 83(Y) N26°13.75' W97°39.14' 025° 22.9 NM to fld. 32/5E.

PORTLAND

HUNT (9R5) 2 NW UTC-6(-5DT) N27°53.18' W97°20.97' **BROWNSVILLE**
38 NOTAM FILE SJT
RWY 14L-32R: H2350X20 (ASPH-DIRT) S-9 0.7% up NW
RWY 14L: Road. Rgt tfc.
RWY 32R: Brush.
RWY 14R-32L: 1400X60 (TURF-GRVL)
RWY 14R: Rgt tfc.
NOISE: Noise abatement procedures in effect. Call arpt manager at 361-643-3950.
AIRPORT REMARKS: Unattended. Rwy 14R-32L CLOSED indef. Crops on both sides of rwy. Wind turbines N of arpt. Rwy 14L-32R has severe grass encroachment, pot holes, and loose gravel on rwy. Rwy 32R, first 200 ft turf. Rwy 14R-32L heavy rutting along entire rwy length. Rwy 14L-32R limited line of sight btn thrs; southern 600' of rwy drops off approx 8 ft. Rwy 32R ground drops off approx 10 ft at thld. Rwy 14L nstd thr bar 183 ft fm rwy end.
AIRPORT MANAGER: 361-643-3950
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Corpus Christi Apch at 361-299-4230.

POSSUM KINGDOM (See GRAFORD on page 339)

POST-GARZA CO MUNI (5F1) 2 E UTC-6(-5DT) N33°12.20' W101°20.29' **DALLAS-FT WORTH**
2545 B NOTAM FILE FTW L-6H
RWY 17-35: H4200X60 (ASPH) S-16 MIRL
RWY 17: PAPI(P2L)—GA 3.0° TCH 20'.
RWY 35: Road.
RWY 06-24: H2210X60 (ASPH) S-16 MIRL 1.0% up SW
RWY 06: Trees.
RWY 24: Fence.
AIRPORT REMARKS: Attended intmnt. Deer and feral hogs on and invof arpt. Rwy 06-24 and Rwy 17 pavement poor, seal coat spalling, loose stones and asphalt.
AIRPORT MANAGER: 806-759-7561
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.
RADIO AIDS TO NAVIGATION: NOTAM FILE LBB.
LUBBOCK (L) (L) VORTACW 109.2 LBB Chan 29 N33°42.30' W101°54.84' 125° 41.7 NM to fld. 3310/11E.
VOR unusable:
040°-050° byd 38 NM blo 5,300'
210°-260° byd 25 NM blo 6,000'

PRESIDIO

BIG BEND RANCH STATE PARK (3T9) 23 E UTC-6(-5DT) N29°28.27' W103°56.19' **EL PASO**
4250 NOTAM FILE SJT H-7A, L-6J
RWY 08-26: H5500X80 (ASPH/GRVL)
RWY 08: Brush.
RWY 26: Brush.
AIRPORT REMARKS: Unattended. Arpt located 26 miles from ranch gate, road very rough. Upon arrival, check in at ranger station, 1 mile from arpt. Remote area, no cell phone coverage. Rwy 08-26 loose stones on rwy.
AIRPORT MANAGER: 432-358-4444
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.